SHIP TODAY

Work Orde									Page 1
Revision ID:	D206-642-34' Wearshoe	7		Accept			Setup	Start Stop	
	11/9/2010 11/9/2010	Start Qty: 3.00 Req'd Qty: 3.00			Cust Item II Customer:	D:			(1881) 81 81 81 81 81 81 81 81 81 81 81 81 81
Approvals:		n:	Date: <u>0-11-9</u>	Tooling: SPC (Y/N):		ite:	 Run	Start Stop	
Sequence ID/ Work Center II Draw Nbr)	Operation Description sion Nbr		Set Up/ Run Hours	Tool ID	Tool # Pla Coo	pt Re Qt		Reject Insp. Number Stamp
DC Document Control		Memo Photoco CHG002	py bluefile and create labels per	0.00 0.00 PPP D206-642-347	Siolulos		r da	H N	F 10-11-0
110 Packaging Packaging		Pick Kit Memo		0.00			 Mala	rSf	38

0.00

120

Quality Control

QC4- 100% Inspect kits for completeness

Memo

Dart Aerospace Ltd

W/O:			WORK ORDER CHANGES									
DATE	STEP	PRO	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
								. rod mg.				
			J					·				
Part No	•	PAR #:	Fault Categ	ory:	NCR: Yes	No DQ	٨:	_ Date: _				
			Disposition: QA			QA: N/C Closed: Date:						
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCR)						
DATE	STEP	Description of NC	1	on B	Verific		Approval	Approval				
DAIL	J.L.	Section A	Initial Chief Eng	Action Description Chief Eng	Date	Section	on C	Chief Eng	QC Inspector			
					,							
					i i							

Work Order ID 63671

*Tuesday, November 09, 2010 1:39:27 PM

Item ID:

D206-642-347

Accept

Setup Start

Stop



Revision ID:

Item Name:

Wearshoe

Start Date: 11/9/2010

Required Date: 11/9/2010

Start Qty: 3.00 **Req'd Qty: 3.00**

Identify and pack for shipping as per PPP D206-642-347

Cust Item ID:

Customer:

Tool ID

Reference:

Approvals:

Process Plan: Date: Tooling:

Date:

Run Start



QC: ____

Date: _____

SPC (Y/N):

Date: ____

Accept

Reject Qty

Sequence ID/

Work Center ID

130

Packaging

Packaging

Operation Description

Set Up/ **Run Hours**

0.00

Tool # Plan Code

Qty

Reject

Stop

Number Stamp

140

QC

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

Memo

0.00

Dart Aerospace L	td
------------------	----

W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO	PROCEDURE CHANGE					Approval Chief Eng / Prod Mgr	Approval QC Inspector				
						· · · · · · · · · · · · · · · · · · ·		F100 Migi	·				
								}					
Part No: PAR #:		PAR #:	Fault Cate	ategory: NCR: Yes No DQA: [Date: _					
Resolution:			Dispositio	QA: N/C C	losed:	Date:							
NCR:			WORK ORD	ER NON-CONFORM	ANCE (NC	R)							
DATE	CTED	Description of NC		tion B	Verif	ication	Approval	Approval					
DATE	STEP	Section A	Initial Action Description Chief Eng Chief Eng		otion Sign & Date		ction C	Chief Eng	QC Inspector				
,													
		4-4-4-											
Ī						1							

Work Order ID: 63671

Parent Item:

D206-642-347

Parent Item Name: Wearshoe



Start Date: 11/9/2010

Required Date: 11/9/2010

Page 1

Start Qty: 3.00

Required Qty: 3.00

Comments:

IPP RevA: New issue DD verified by:EC

IPP Rev:B as

	per IIN revN DD v	erified by:JLM											
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3537-1 , Wearpad		Manufactured	No			110	Each	32.0000	6-	18	Je.		
				<u>Locatior</u> FP017	1	Loc	<u>Otv</u> 32	Loc Code			1		
D3537-3 3Wearpad		Manufactured	No		62661 63313	110	9 23 Each	30.0000	1	3 3/11/25			- -
4), real place				Location FP17	61674	Loc	Oty 30 10 20	Loc Code	<u>)</u>)	\ - -		
D3535-11 Wearshoe		Manufactured	No			110	Each	6.0000		13 Vulgs	p(34)		
				Location FP019	n 57261	<u>Loc</u>	Oty 6 6	Loc Code	e.	<u>.</u>	_		

Dart Aerospac	e Ltd
---------------	-------

W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO	CEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
								Prod Mgr	<u> </u>				
									<u> </u>				
Part No: PAR #:			Fault Cate	egory:	_ NCR: Yes	NCR: Yes No DQA: Date:							
	R	esolution:	on:	_ QA: N/C Clo	osed:		Date: _						
NCR:		V	VORK ORD	ER NON-CONFORMA	ANCE (NCR)							
		Description of NC Section A Initial Action Description				Verific	ation	Approval	Approval				
DATE	STEP	Section A	Initial Chief Eng	Sign & Date	Sign & Section		Chief Eng	QC Inspector					
					9								
					į								
					•								
	-												

Tuesday, November 09, 2010 1:39:26 PM

Work Order ID: 63671 Parent Item: D206-642-347 Parent Item Name: Wearshoe **Start Date:** 11/9/2010 Required Date: 11/9/2010 Required Qty: 3.00 Start Qty: 3.00 D3536-11 : Manufactured 110 Each 12.0000 Tasket Location Loc Qty Loc Code FP011 57867 ST497A 46715 4 D3535-23 Manufactured No 110 18.0000 Each Location Loc Qty Loc Code FP 61830 4 FF021 13 62706 13 D3536-23 Manufactured 110 Each 16.0000 **A**Gasket Location Loc Qty Loc Code FP011 16 15 63391 D3535-35 Manufactured No 110 Each 20.0000 Location Loc Qty Loc Code FP018 20 60865 62<u>461</u> 11

62969

Dart Aerospace Ltd

W/O:			WC	RK ORDER CHANGES	3						
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
		·									
Part No		PAR #:	Fault Cate	gory:	NCR: Yes No DQA: Date:						
Resolution:			Disposition: QA								
NCR:			WORK ORD	ER NON-CONFORMAN	ICE (NC	R)					
DATE	STEP	Description of NC		Corrective Action Section			cation	Approval	Approval		
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section Action Description Chief Eng	B Sign Date	& Sect	cation ion C	Approval Chief Eng	Approval QC Inspector		
DATE	STEP	Description of NC Section A	Initial	Action Description	Sign	& Sect					
DATE	STEP	Description of NC Section A	Initial	Action Description	Sign	& Sect					
DATE	STEP	Description of NC Section A	Initial	Action Description	Sign	& Sect					
DATE	STEP	Description of NC Section A	Initial	Action Description	Sign	& Sect					
DATE	STEP	Description of NC Section A	Initial	Action Description	Sign	& Sect					
DATE	STEP	Description of NC Section A	Initial	Action Description	Sign	& Sect					
DATE	STEP	Description of NC Section A	Initial	Action Description	Sign	& Sect					
DATE	STEP	Description of NC Section A	Initial	Action Description	Sign	& Sect					

Zuesday, November 09, 2010 1:39:26 PM

Work Order ID: 63671

Parent Item:

D206-642-347

Parent Item Name: Wearshoe



58683 62462 **Start Date: 11/9/2010**

Required Date: 11/9/2010

Start Qty: 3.00

Required Qty: 3.00



Manufactured

110 Each 10.0000

Nο	

Loc Qty 10 9 110 Each

Loc Qty

Loc Code

25.0000

Loc Code

1 162

₁,MS27039C1-08

₹3_{SCREW}

NAS1149C0332

Purchased

Purchased

921.0000

	FP	
		115336
	ST293	
		115589
	•	116022
		19185
No		

Location

Location

FP012

MUSE 32 1Sh



AN960C10L

Location Loc Oty Loc Code ST245 25 107534 25

162

Dart Aerospace Ltd

W/O:		The state of the s	WORK ORDER CHANGES							
DATE	DATE STEP			PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
		_						•	i	
				100		•				
								}		
						4 ,				
Dort No	_		DAD #.	Fault Catagony	NOD. V	a Na DÓ	· A -	Doto		

Part No:		_ PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
	Resolution:		Disposition:	QA: N/C Closed:	Date:
NCR:		WC	ORK ORDER NON-	CONFORMANCE (NCR)	

NCH:												
	STEP	Description of NC		Corrective Action Section B	Verification	Approval	Approval					
DATE		Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	Approval QC Inspector				
				*								
•												
						,						
							}					
* '	1	I		I	1		1	1				

206 L/L-1/L-3/L-4/407 LOW & HIGH GEAR SKIDTUBES 4.5

Item	Qty -311	Qty -312	Qty -341	Qty -347	Qty -013	Part Number	Description
	Х					D206-642-311	SKIDTUBE INSTALLATION, LH
		Х				D206-642-312	SKIDTUBE INSTALLATION, RH
	1	1	Х	-		D206-642-341	SKIDTUBE
				X		D206-642-347	WEARSHOE KIT (REPLACES -343)
	1	1			X	D206-648-013	GROUND HANDLING KIT
1			1			D2650-5	SKIDTUBE ASSEMBLY
2A			14			D2651-1	* PLUG (1)
2B			14			D2651-3	* O-RING (1)
3			1			D2646	* AFT CAP (1)
4			2			MS27039-1-08	* SCREW (1)
5			2			AN960JD10L	* WASHER (1)
						D2932-1	SADDLE, FWD OUT, LH
6	1					D2932-1	SADDLE, FWD OUT, RH
6		1				D2932-2 D2933-1	SADDLE, FWD IN, LH
7	1						SADDLE, FWD IN, RH
7		1		ļ		D2933-2 D2938-1	SADDLE, AFT OUT, LH
8	1			 			SADDLE, AFT OUT, RH
8		1	<u></u> .			D2938-2	SADDLE, AFT IN, LH
9	1	ļ,		<u> </u>		D2939-1	SADDLE, AFT IN, EH
9		1		 		D2939-2	BOLT
10	8	8		ļ		AN3-41A D2652	BUSHING
11	16	16					NUT (OR MS21042L3)
12A	8	8				MS21042-3	WASHER
128	8	8				AN960JD10	* BOLT (2)
13	4	4				AN5-10A (OR AN5-11A)	* BOLT (2)
14	4	4				AN5-11A (OR AN5-12A)	WASHER
15	8	8		1		AN960JD516	BOLT
16	12	12		1		AN4-6A	WASHER
17	24	24		<u> </u>	<u> </u>	AN960JD416	NUT (OR MS21042L4)
18	12	12			ļ	MS21042-4	NOT (OR MIS21042L4)
20A			6	6		D3537-1	WEARPAD (REPLACES D2648-3)
21A		-	1	1		D3537-3 /	WEARPAD (REPLACES D3429-1)
22A			1	1		D3535-11	WEARSHOE (REPLACES D2656-11)
22A 22B		 	1	1		D3536-11 /	GASKET
23A			1	1		D3535-23	WEARSHOE (REPLACES D2656-23)
23B		 -	 	1		D3536-23	GASKET
24A			1	1		D3535-35	WEARSHOE (REPLACES D2656-35)
24B			. 1	1		D3536-35	GASKET
26A	 		54	54		MS27039C1-08	SCREW
26B		 	54	54		AN960C10L	WASHER
26C	 		54			ALS7-1032-130	*INSERT (1)
200							(or AKS4-1032-130, ALS4-1032-130, AELS-1032-130)
30	1	1		 		D3407-043	TOW RING ASSEMBLY (REPLACES D2968-043)
31	1	1				D3456-1	WASHER
32	1	1				D3457-1	WASHER
33	l i	1				MS21043-4	NUT
34	1	1				AN4C5A	BOLT
35	1	1		1		AN960C416	WASHER
36	1	1		<u> </u>		D3413-1	RING (REPLACES D2655)
			ļ	 	_	D2712	SET SCREW
37	10	10	 	 		D2712	SADDLE SPACER
38	2	2	 			D2934	SADDLE SPACER
39	2	2			 	D2935	SADULL SPACEN
40	 	 		 	2	D3414-041	GHW LUG (REPLACES D2659)
41	 	 	 	 	4	AN3C37A	BOLT
41	 	 	 	 	8	D2652	BUSHING
		 	 	 	4	MS21043-3	NUT
43		 	 	 	4	AN960C10	WASHER
44	l	J	L	1		VI1900C10	Timorium

NOTES: (1) DENOTES THAT PART IS INCLUDED WITH D2650-5 ASSEMBLY ABOVE (2) CHOICE OF BOLT WILL DEPEND ON CROSSTUBE (SEE INSTALLATION PROCEDURE)

• COPYRIGHT © 2000 BY DART AEROSPACE USA, INC •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC

Revision:

Date: 09.09.09